

**Tiffany, Bruce**

---

**From:** Tiffany, Bruce  
**Sent:** Friday, May 19, 2006 9:48 AM  
**To:** Renaud, Rick  
**Subject:** RE: Sample Sites at KCIA

Okay. Thanks for clarifying that.

---

**From:** Renaud, Rick  
**Sent:** Friday, May 19, 2006 9:45 AM  
**To:** Tiffany, Bruce  
**Subject:** RE: Sample Sites at KCIA

ok to include 1741. The others discharge into the city system or are on the Boeing lease.

---

**From:** Tiffany, Bruce  
**Sent:** Wednesday, May 17, 2006 12:14 PM  
**To:** Renaud, Rick  
**Subject:** Sample Sites at KCIA

Hi Rick;

Looking at the locations of the stormwater vaults, it appears to me that we should sample a couple of catch basins to ensure that we have complete coverage. I think we should sample the following catch basins:

- CB1741 (This captures the line that drains the aircraft parking area and is located between Vaults 1680 and 1756)
- CB1554 and CB1575 (Provides coverage in the northwestern portion of KCIA)

Please see the attached file that shows the proposed sample locations. I have also added some notations for our GIS/graphics person. Please let me know your thoughts on adding these sample locations.

Also, I am still waiting to hear from our lab on analytical costs, but I should have the answer shortly.

Thanks,

Bruce

5/19/2006

---

KCSlip4 57051

SEA423357

**Tiffany, Bruce**

---

**From:** Tiffany, Bruce  
**Sent:** Wednesday, May 17, 2006 12:14 PM  
**To:** Renaud, Rick  
**Subject:** Sample Sites at KCIA  
**Attachments:** BT\_Draft-KCIA-Sample\_Sites.pdf

Hi Rick;

Looking at the locations of the stormwater vaults, it appears to me that we should sample a couple of catch basins to ensure that we have complete coverage. I think we should sample the following catch basins:

- CB1741 (This captures the line that drains the aircraft parking area and is located between Vaults 1680 and 1756)
- CB1554 and CB1575 (Provides coverage in the northwestern portion of KCIA)

Please see the attached file that shows the proposed sample locations. I have also added some notations for our GIS/graphics person. Please let me know your thoughts on adding these sample locations.

Also, I am still waiting to hear from our lab on analytical costs, but I should have the answer shortly.


Thanks,

Bruce

5/17/2006

KCSlip4 57052

SEA423358



Structures